

Exhibit J: Exposed face of fill embankment at site of slope failure near South 160<sup>th</sup> Street showing distinct layering and lack of homogeneity, 28 January 2002

Note: Exposed face in photograph is approximately 4 feet high by 3 feet wide.



**AR 026300**